

11300 (7)

MAIN/PDL/a1m
11300

JAN 1 3 1984

MEMORANDUM FOR THE COMMANDING GENERAL

Via: (1) Assistant Chief of Staff, Facilities
(2) Chief of Staff

Subj: Report of Damage Due to Broken Pipes from Heavy Freeze 25-26 December 1983

Ref: (a) NAVFAC Specification N62470-81-B-1047

Encl: (1) Family Housing Units with Broken Pipes
(2) Computations

1. Background. On 25-26 December 1983 the temperature in Jacksonville dropped to 10°F accompanied by westerly winds up to 28 knots (wind-chill temperature -31°). This represented a 22-year low. Three hundred and thirty-six family housing units suffered frozen/broken pipes, and subsequent water damage. The purpose of this report is to explore the cause and make recommendations to minimize the effect of damage in future cold snaps.

2. Findings.

- a. 336 family housing units suffered broken pipes. See enclosure (1).
- b. 191 of these units were in Tarawa Terrace II. See enclosure (1).
- c. 39 of these units were in Tarawa Terrace I. See enclosure (1).
- d. 46 of these were at MCAS(H). See enclosure (1).
- e. 60 of these were in all other housing areas. See enclosure (1).
- f. The amount of damaged units by percentage: See enclosure (2).

<u>Area</u>	<u>% of Area Units</u>	<u>% of Breaks</u>
(1) Tarawa Terrace I	4.2%	11.6%
(2) Tarawa Terrace II	20.6%	56.8%
(3) MCAS(H)	10.5%	13.7%
(4) Paradise Point, Watkins Village, Capeharts, Midway Park, Rifle Range, Court-house Bay	2.7%	<u>17.9%</u>
(5) Base overall	7.5%	100.00%

ANSWER MAIL

“我就是想让你知道，你不是唯一一个被我爱着的人，我还有其他的朋友。”

在這裏，我們將會看到一個簡單的範例，說明如何在一個應用程式中，將一個字串轉換成一個數值。

清江一曲抱村流，長安此地分南北。

1996-1997 学年第二学期期中考试卷

(1) *Brachynopus* sp. 2, a large and hairy fly from the hills, April 1912.

10. The following table summarizes the results of the study.

Subj: Report of Damage Due to Broken Pipes from Heavy Freeze 25-26 December 1983

g. 52.8% of the breaks in Tarawa Terrace II were pipes in the attics and caused damage to the structure (enclosures (1) and (2)).

h. 82% of the Tarawa Terrace II units with structural damage due to broken pipes in the ceiling had been remodeled under Contract N62470-81-B-1047.

3. Opinions.

a. The breakage in most areas was within reasonable limits expected for the extreme low temperature (22-year low).

b. The breakage in Tarawa Terrace II is not within those limits. Over half of all the broken pipes were in an area that has only one-fifth of the housing units.

c. That the Tarawa Terrace units have an oversized air ventilation system in the attic.

4. Facts.

a. The reference required insulation on all above ground piping (page 15181-3).

b. The piping had not been insulated to comply with the design specification.

c. Documentation that the Contract N62470-81-B-1047 had been modified removing the requirement for insulation could not be obtained.

5. Conclusion.

a. That the primary cause of the damage was due to the cold and wind-chill.

b. That in Tarawa Terrace II the amount of damage was significantly increased by a lack of sufficient insulation on the pipes.


c. That the amount of damage in the future could be minimized by proper installation of insulation, as per the original NAVFAC design.

d. That the large air vents in the end walls allowed the wind-chill temperature to become a factor on those houses with the end walls facing into the wind.

6. Recommendations.

a. That the pipes in the family housing units be insulated in accordance with the NAVFAC specifications.

b. That a formal investigation be conducted to determine why these pipes were not insulated in accordance with the NAVFAC specifications.



NAIN/PDL/alm
11300

Subj: Report of Damage Due to Broken Pipes from Heavy Freeze 25-26 December 1983

c. That the investigation further examine the following:

(1) Will the trusses that were cut to make room for duct work support the ceiling and roof with a snow load?

(2) Are pipes in the walls insulated only in places that are easy to inspect?


(3) Will the expansion chambers that are water logged due to faulty installation be susceptible to future freezing?

d. That an engineering study be conducted to determine if the vents in the end walls or soffits should be closed and a temperature controlled power vent be installed in the roof to provide air circulation during the summer.

Very respectfully,

J. T. MARSHALL

Copy to:
Dir, FamHsg (Provided on 26 Jan 84)



1/13


W = Westminster
G = Guyler

UNIT

Tarawa Terrace II


CONT

1	TT-II 2007	DIN + BATH room ceiling	W
2	TT-II 2031	wall	W
3	" 2038	Kit Ceiling	W
4	" 2044	Kit Ceiling	W
5	" 2064	Ceiling	W
6	" 2066	sht Rock on wall in hall/ceilings	W
7	" 2068	wall	W
8	" 2113	wall	W
9	" 2120	wall	W
10	" 2146	wall	G
11	" 2164	Bath ceiling	G
12	" 2180	wall	G
13	" 2184	wall	G
14	" 2186	wall	G
15	" 2196	Bath ceiling	G
16	" 2202	wall	G
17	" 2210	wall	G
18	" 2212	Hall Kit + LR Ceiling	G
19	" 2214	wall / pipe	G
20	" 2228	wall / pipe	G
21	" 2234	wall / pipe	G
22	" 2236	wall	G
23	" 2259	wall	W
24	" 2272	Kit Ceiling	G
25	" 2276	sht Rock ceiling	G
26	" 2292	Tape + Fonest Sheet Rock	G
27	" 2304	wall	G
28	" 2308	wall	G
29	" 2312	Kit Ceiling	G
30	" 2348	Kit Ceiling ENGLOSURE (1)	W




2/13

31	II-II	2356	Kit ceiling	w
32	"	2358	Kit ceiling	w
33	"	2362	Ceilings	w
34	"	2383	Kit Ceiling	w
35	"	2389	Kit Ceiling	w
36	"	2413	Kit Ceiling	w
37	"	2405	BATH Ceiling	w.
38	"	2415	wall	w
39	"	2418	Ceilings	w.
40	"	2422	Ceilings	w.
41	"	2432	wall	w
42	"	2434	Kit Ceiling	w
43	"	2436	Bed Room Ceiling	w
44	"	2438	HALL CLOSET ceiling	w
45	"	2440	wall	w
46	"	2442	wall	w
47	"	2421	Ceiling	w
48	"	2518	Bed Room Ceiling	w
49	"	2521	wall	w
50	"	2534	Kit + Hall Ceiling	w
51	"	2536	Kit ceiling	w
52	"	2538	Kit Ceiling	w
53	"	2542	wall	w
54	"	2548	Kit + LR Ceiling	w
55	"	2552	Kit, LR + BR Ceiling	w
56	"	2557	Ceilings	w
57	"	2562	Ceiling	w
58	"	2564	wall	w
59	"	2566	Ceiling	w
60	"	2572	Kit Ceilings	ENCLOSURE 115 w



3/13


61	II-2585	Kit Ceiling	w
62	" 2590	Ceiling	w
63	" 2599	Ceiling	w
64	" 2560	Kit + LR Ceiling	w
65	" 2618	Ceiling	w
66	" 2620	wall	w
67	" 2627	wall	w
68	" 2641	Kit Ceiling	w
69	" 2645	wall	w
70	" 2647	Ceiling	w
71	" 2657	Kit Ceiling	w
72	" 2664	wall	w
73	" 2687	wall	w
74	" 2697	wall	w
75	" 2703	KIT + BATH Ceiling	w
76	" 2708	Ceiling	w
77	" 2710	Ceiling	w
78	" 2715	Ceiling	w
79	" 2718	Kit Ceiling	w
80	" 2719	Kit Ceiling	w
81	" 2743	wall	w
82	" 2780	Kit Ceiling	w
83	" 2783	wall	w
84	" 2785	Ceiling	w
85	" 2808	ON RM Ceiling	w
86	" 2809	Ceiling	w
87	" 2832	Ceiling	w
88	" 2834	ON RM ceiling	w
89	" 2844	wall	w
90	" 2851	ON RM / LR ceiling ENCLOSURE 111	w



9/3

91	II-II 2853	DN rm ceiling	w
92	2855	wall	w
93	2864	wall	w
94	2874	DN rm Ceiling	w
95	2877	Ceiling	w
96	2915	BATH room ceiling	w
97	2925	Ceiling	w
98	2928	4th floor Ceiling	w
99	2929	wall	w
100	2930	DN rm / LR ceiling	w
101	2932	L-R ceiling	w
102	2934	wall	w
103	2939	wall	w
104	2947	Ceiling	w
105	2957	Dining + living room ceiling	w
106	2973	Ceiling	w
107	2989	KIT Ceiling	w
108	2997	wall	w
109	2998	wall	w
110	2922	KIT Ceiling	w
111	3007	Ceiling	w
112	3009	Ceiling	w
113	3012	wall	w
114	3016	wall	w
115	3018	DR Ceiling	w
116	3023	Ceiling	w
117	3028	Ceiling	w
118	3030	Ceiling	w
119	3032	Ceiling	w
120	3034	wall	w


ENCLOSURE (1)



5/13


121	77-II 3040	Ceiling	W
122	3042	wall	W
123	3045	wall	W
124	3048	wall	W
125	3154	wall	G
126	3156	wall	G
127	3170	Kit & Hull Ceiling	G
128	3206	Kit ceiling	G
129	3222	Dining Room Ceiling	G
130	3227	Dining Room Ceiling	G
131	3231	BATH room ceiling	G
132	3235	wall	G
133	3239	wall.	G
134	3244	BATH room ceiling	W
135	3301	wall	W
136	3304	Kit & Liv Rm Ceiling	W
137	3305	BR + BATH Ceilings	W
138	3307	Ceiling	W
139	3309	wall	G
140	3310	wall	G
141	3311	Ceiling	G
142	3313	wall	G
143	3316	wall	G
144	3317	wall	G
145	3319	wall	G
146	3321	wall	G
147	3342	wall	G
148	3325	wall	G
149	3327	wall	G
150	3329	wall	G

ENCLOSURE 111




6/13

151	TT-II 3361	wall	G
152	3371	wall	G
153	3375	Bed Room Ceiling	G
154	3376	wall	G
155	3385	wall	G
156	3386	wall	G
157	3388	wall	G
158	3390	wall	G
159	3312	wall	G
160	3407	wall	G
161	3408	wall	G
162	3411	Hull & LR Ceiling	G
163	3412	wall	G
164	3413	Ceiling	G
165	3420	wall	G
166	3422	wall	G
167	3427	wall	G
168	3428	Bed Room Ceiling	G
169	3429	wall	G
170	3431	wall	G
171	3432	Closet Ceiling	G
172	3435	wall	G
173	3436	wall	G
174	3438	wall	G
175	3440	Ceilings	G
176	3500	wall	G
177	3528	wall	G
178	3536	wall	G
179	3545	wall	G
180	3552	wall	ENCLOSURE III G




71
13



8/83


Yarama Terrace I

UNIT		CONST
1.	TT-1 137	wall
2.	" 141	Ceiling,
3.	" 147	wall
4.	" 181	Ceiling
5.	" 185	wall
6.	" 245	Bath Ceiling
7.	" 251	wall
8.	" 663	Kitt + LR Ceiling
9.	" 708	wall
10.	" 751	wall
11.	" 755	Hall Ceiling
12.	" 794	1SF Sht Rock ceiling
13.	" 948	BATH + HALL closet ceiling
14.	" 950	Ceiling, Sheetrock & insul. + Paint
15.	" 955	wall
16.	" 978	wall
17.	" 980	wall
18.	" 991	wall
19.	" 1014	Bedroom Ceiling
20.	" 1016	Bedroom Ceiling
21.	" 1059	wall
22.	" 1086	Bedroom Ceiling
23.	" 1088	wall
24.	" 1106	wall
25.	" 1202	wall
26.	" 1208	wall
27.	" 1283	wall
28.	" 1305	wall
29.	" 1321	Ceiling (sht rock)
30.	" 1343	wall
		ENCLOSURE 111



9/13

31	77-1	1367	Dining Room Ceiling
32	77-1	1379	Ceiling
33	77-1	1429	wall
34	77-1	1518	wall
35	77-1	1524	wall
36	77-1	1532	wall
37	77-1	1530	wall
MOWY PARK			
1	LCH	1530	Pipes
2	LCH	1432	Pipes
3	LCH	1524	Hanwood floor / Pipes / PLASTER MOW wall
4	LCH	1367	Pipes
5	LCH	702	Pipes
6	LCH	774	Pipes
7	LCH	1701	Pipes
8	LCH	1702	Pipes
9	LCH	1713	Pipes
38	77-1	832	Ceiling
39	77-1	1302	wall




10/13

AIR STATION


DAMAGE

1	AS 2051	CARPORT Ceilings
2	AS 2049	KIT Ceilings
3	" 1051	only pipes
4	" 1059	Insulation replacement
5	" 1087	only pipes
6	" 2031	Carport Ceilings
7	" 2047	Pipes
8	" 2077	Pipes
9	" 2080	Pipes
10	" 2120	KIT Ceilings
11	" 2086	Ceilings in hallway
12	" 2094	Pipes
13	" 2081	Plywood area & by front door
14.	" 2066	Pipes
15	" 1254	Laundry Room Ceiling & Floor tiles
16	" 2071	Plywood by front door
17	" 1132	Pipes
18	" 2048	Pipes
19	" 1245	Pipes
20	" 2052	Pipes
21	" 1094	Pipes
22	" 2021	Pipes
23	" 1095	Ceilings, Plaster
24	" 1314	LR Ceiling & Floor
25	" 1176	Ceilings in furnace Room
26	" 1165	Insulation needs replaced
27	" 1293	Pipes
28	" 1129	Pipes
29	" 1272	Pipes
30	" 1103	Pipes

ENCLOSURE 11



11/13




12/13

ALL OTHER AREAS

DAMAGE

1	PP 2412	BROKEN PIPE
2	2613	Broken Pipe
3	2622	Broken Pipe
4	2719	Broken Pipe
5	3346	BROKEN Pipe
6	5225	Broken Pipe
7	3000	Broken Pipe
8	5082	Broken Pipe
9	2520	Broken Pipe
10	3365	broken Pipe
11	5752	Broken Pipe
12	5702	Broken Pipe
13	5067	Broken Pipe
14	5818	Broken Pipe
15	61.898	BROKEN Pipe
16	3361	Broken Pipe
17	5581	BROKEN Pipe
18	61678	Broken Pipe
19	5143	broken pipe
20	5825	Broken pipe
21	3022	Broken pipe
22	3019	Broken pipe
23	3313	broken pipe
24	2703	broken pipe
25	2711	broken pipe
26	2619	broken pipe
27	2311	broken pipe
28	2229	broken pipe
29	2225	broken pipe
30	2223	broken pipe


ENCLOSURE 111



13/13

31	2112		Pipes
32	2115		Pipes
33	2303		Pipes
34	2510		Pipes
35	2122		Pipes
36	5238		Pipes
37	2217		Pipes
38	2717		Pipes
39	3345		Pipes
40	3372		FLOOR TILE IN KITCHEN/WALKIN LR HALLWAY FLOOR
41	3361		Pipes
42	3324		Pipes
43	2917		Pipes

1	BB	27	minor / Pipes
2	BB	18	minor / Pipes
3	BB	21	minor / Pipes
4	BB	17	minor / Pipes
5	RR	41	minor / Pipes
6	RR	40	minor / Pipes
7	RR	43	minor / Pipes
8	RR	42	minor / Pipes



COMPUTATIONS

Tarawa Terrace I 922 units 39 breaks

$$\frac{39}{922} \times 100 = 4.23\%$$

$$\frac{39}{336} \times 100 = 11.6\%$$

Tarawa Terrace II 924 units 191 breaks

$$\frac{191}{924} \times 100 = 20.67\%$$

$$\frac{191}{336} \times 100 = 56.8\%$$

MCAS(H) 435 units 46 breaks

$$\frac{46}{435} \times 100 = 10.57\%$$

$$\frac{46}{336} \times 100 = 13.7\%$$

Other Areas 2173 units 60 breaks

$$\frac{60}{2173} \times 100 = 2.7\%$$

$$\frac{60}{336} \times 100 = 17.9\%$$

Base-wide 4454 units 336 breaks

$$\frac{336}{4454} \times 100 = 7.5\%$$

1940 SPRING 1941